

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form approved.  
Budget Bureau No. 42-R1424.  
3. LEASE DESIGNATION AND SERIAL NO.  
NM 16806  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Ling-Federal  
9. WELL NO.  
1  
10. FIELD AND POOL, OR WILDCAT  
Wildcat  
11. SEC., T., R., M., OR B.L. AND  
SURVEY OR AREA  
3-15S-29E  
12. COUNTY OR PARISH  
Chaves  
13. STATE  
NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a well or to plug back a reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry hole  
2. NAME OF OPERATOR  
Dalport Oil Corp.  
3. ADDRESS OF OPERATOR  
3471 First National Bank Bldg., Dallas, Texas 75202  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
990' FNL 1880' FWL

14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3,858 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)

PULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON\*  
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-4-83 Well drilled to 1,870', Ran radioactivity log. Verbal permission given by George Stewart to plug. Will plug as follows:

1700-1800' 100 sx plug (25 sx)  
925-1025' 100 sx plug (25 sx) in and out of base salt  
160-260' 100 sx plug (25 sx) in and out of surface casing  
0-10 10 sx plug

Will erect 4' steel marker showing name and location and will clean location.

RECEIVED  
APR 11 1983

MINERAL RESOURCES SERVICE  
ROOSEVELT, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

APPROVED

TITLE

Geologist

DATE

4-6-83

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

TITLE

DATE

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY

APR 21 1983

For James A. Williams  
ACTING DISTRICT MANAGER

\*See Instructions on Reverse Side