Form 3160-5	ITED STATES SUBMIT IN TRIPLICA	Form approved. CSC Budget Bureau No. 1004-0135
THOMAN AND AND AND AND AND AND AND AND AND A	IN ATT COME RODUCTOR	Expires August 31, 1985
(Formeriy-9-331)	BUREAU OF LAND MANAGEMENT DES WOISTDD)	5. LEASE DESIGNATION AND SERIAL NO.
	BUREAU OF LAND MANAGEMENT Artesis, NN 88210	N M- 18826
AUG 3 0 1985	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do the Geothe	s form for proposals to drill or to deepen or plug back to	
ABTESAKODE	Servoir Use "APPLICATION FOR PERMIT-" for such proposals.)	-
. OIL GA		7. UNIT AGREEMENT NAME
WELL WE	LL OTHER Dry Hole	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Read & Stevens,		DIAMOND FEDERAL 9. WELL NO.
3. ADDRESS OF OPERATOR		1
P.O. Box 1518, Roswell, NM 88201 4. LOCATION OF WELL(Report location clearly and in accordance with State		10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL(Report location clearly and in decordance in a second secon		Undesignated Diamond Mound (14)
		11. SEC. T.,R.,M.,OR BLK. AND
At surface 1980' FNL and 660' FEL		SURVEY OR AREA
		Sec. 33-15S-27E
14. PERMIT NO.	15. ELEVATIONS(Show whether DF,RT,GR,etc.)	12. COUNTY OR PARISH 13. STATE
	3515' GR	Chid Vos
16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data		
	NOTICE OF INTENTION TO: S	UBSEQUENT REPORT OF:
	-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
TEST WATER SHUT	MULTIPLE COMPLETE FRACTURE TREATM	ALTERING CASING
FRACTURE TREAT	SHOOTING OR ACT	DIZING ABANDONMENT*
SHOOT OR ACIDIZ	Other) Pluc	back & set CIBP X
REPAIR WELL	(NOTE:Report r	esults of multiple completion on Well
(Other)	Completion or	Recompletion Report and Log form.)
17 DESCRUBE PROPOS	ED OR COMPLETED OPERATIONS(Clearly state all pertinent details, a	and give pertinent dates, including
satimated date of starting any proposed work. If well is directionally diffice give substantial		
and true vertical depths for all markers and zones pertinent to this work.)*		
		be Bron to null RBP
7-23-85	Puiled 224 3/4" rods & 66 7/8" rods & pump, 234jts 2 3/8"-4.7# ti	
	Pulled RBP, set CtBP @ 7250', spotted 3sx cmt on CtBP, 45' fill,	circ hole w/salt gel, pull
7-24-85	20 stands tbg, SDON.	
7-25-85	Pulled tbg, weld on lift sub to csg, csg free @ 36001, cut csg @	3600', csg would not come
	loose, dropped collar locator in hole, pid 140,000#, SDON, left	pull on csg.
	to receive and even wort in hole w/t	ba, could not get inside csg,
7-26-85 Csg would not come loose, cut @ 30001, pld csg, went in hole w/tbg, could not get inside csg, spotted 45sx Class "C" cmt @ 30001, pl tbg, SDON. Peter Chester, BLM, gave verbal approval		
	spotted 45sx Class "C" cmt e 5000", pi rog, 500%, Pore energies	,
	to set plug on top of csg stub.	
7-27-85	7-27-85 Ti w/tbg. Tagged plug @ 2910', spotted 45sx @ 2650', spotted 80sx @ 1800'.	
	a start (10% Deteo NU and prep to perf.	
7-29-85	Tagged plug € 1610'. Circ hole w/10∦ Brine, NU and prep to perf.	•
I hereby certify	that the foregoing is true and correct	
B	TITLE Drilling & Production	Manager DATE 8/9/85
SIGNED	- marcine	
(This space fo	r Federal or State office use)	ACCEPTED FOR RECORD PETER W. CHESTER
	TITLE	DATE
APPROVED BY		
CONDITIONS OF	APPROVAL, IF ANY: *See instructions on Reverse Side	AUG 2 8 1985
		BUREAU OF LAND MANAGEMENT
		BUREAU OF LAND MAINTERA ROSWELL RESOURCE AREA