

45P

RECEIVED

Form 3160-5
(November 1983)
(Formerly 9-331)

OCT 13 '87

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-18826

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
DIAMOND FEDERAL

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT
Undesignated Diamond Mound

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 33-15S-27E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

SUNDY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR
Read & Stevens, Inc.

3. ADDRESS OF OPERATOR
P.O. Box 1518, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with state requirements.* See also space 17 below.)
At surface

1980' FNL and 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3515' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-7-85 TIH w/ 2 3/8"-4.7# tbg to 1523.89'. circ hole w/ 10#/gal Brine w/ 25sx/100bbl salt gel, spot 40sx Class "C" cmt, wait 5hrs, tqd plug @ 1412'.

9-9-85 Trip into 462', spot 40sx Class "C" cmt, 462'-362', across 13 3/8" csg shoe @ 410'. Surface plug, spot 20sx Class "C" cmt, 0'-50', cut off well head, install dryhole marker, cut off deadmen, bust pits, prep to clean up, rip and reseed loc.

Post ID-2
10-23-87
PVA

I hereby certify that the foregoing is true and correct

SIGNED B. [Signature]

TITLE Drilling & Production Manager

DATE 9/10/85

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE Approved as to plugging of the well bore.
Liability under bond is retained until surface restoration is completed.
*See Instructions on Reverse Side

APPROVED
DATE 6/1/87
CHESTER
OCT 6 1987
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA