Submit 3 Copies to Appropriate District Office

## State of New Mexico Ene Minerals and Natural Resources Department

CONDITIONS OF APPROVAL, IF ANY:

OIL CONCEDIATION

C \
-----

DISTRICT	OIL CONSERV	ATION DIVI	SION			
P.O. Box 1980, Hobbs, NM 88240	2040 Pach		I WELL API	۷O.		
DISTRICT II	Santa Fe,	NM 87505	30	30-005-63/00		
P.O. Drawer DD, Artesia, NM 88210				pe of Lease		
				STATE X FEE	_ [ ]	
DISTRICTIII			State Oil B	Gas Lease No.		
1000 Rio Brazos Rd., Aztec, NM 87410			Sociate On a	Gas Lease No.		
014/202/4407/2						
SUNDRY NOTIC	ES AND REPORTS	ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				ne or Unit Agreement Name	********	
	01) FOR SUCH PROPOSA		Marlisue	Queen Unit		
Type of Well:			<del></del>			
OIL GAS GAS						
WELL WELL	OTHER V	VIW				
Name of Operator				⊎Well No.		
M. E. W. Enterprise				1-3		
3Address of Operator				«Pool name or Wildcat		
300 S. Kentucky Ave., Roswell, NM 88201				Double L Queen		
4Well Location						
Unit Letter K : 1560 F	eet From TheFS	Line and _	2500 Feet Fr	om The FWL Line		
24 Section 14S	Township 29	E Range	NMPM	Chaves county		
	#Elevation (Show with	ether DF, RKB, RT, GR, e		,		
	3804					
11 Check Ann	roprioto Davita India	man Nimeron of Ni	-U D 1		**********	
Crieck App	ropriate Box to Indic	ate Nature of No	otice, Report, or O	ther Data		
NOTICE OF INTENTION TO: SUBS			SUBSEQUEN	IT REPORT OF:		
DEDECORA DE MESIA. MASON	PLUG AND ABANDON	NZI				
PERFORM REMEDIAL WORK	1 LOO AND ADAIDON	REMEDIAL V	REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE	COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT			
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB				
OTHER:		OTHER:			۲	
		Onie.k			_	
12Describe Proposed or Completed Operations ( work) SEE RULE 1103.	Clearly state all pertinent details	s, and give pertinent dates	s, including estimated date o	starting any proposed		
•						
1. Notify O.C.D. 24 Hrs. before start P	&A operations.			1 2520		
<ol> <li>MIRU. NU BOP POH w/ tbg.</li> <li>Set CIBP @ 1875 w/ 35 ft. cmt. on</li> </ol>	+n.m.			24 2526 2728		
4. RIH w/ tbg. circ. hole w/ 9.8 # mud				, C. C.		
E DOLLA 4000 # 400 # 4 1	11 14 A 111 - C	(V cen + 01 12	11/11/10/	12 A 62		
5. POH to 1300 ft. spot 100 ft. cmt. pl 6. POH to 400 ft. spot 100 ft. plug (8 7.POH to 30 ft. circ. cmt to surface.	Sign cot on the or sail.	2 Ton	00 - 1700 - 1115	S 1/18 33		
7 POH to 30 ft circ cmt to surface	3/0 Set (@ 340 It.) 4400	a lay essit commit	Pluc 396-296 1061	= 00.8E0 200 TI		
8. Cut off well head & install dry hole r	narker			E CONCEINAGE		
The second of th	numor.		\	E APISO NI		
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
				197		
				18/30 C8/2		
				6/110165		
				Cot 81 - 12 31		
Notific N.M.O.C.D. To I hereby certify that the information above is true	intress Plussing Ope	erutions.				
I hereby certify that the information above is true	and complete to the best of m	y knowledge and belief.	<del>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</del>			
SIGNATURE ( )	1	Agont		20.20.20		
SIGNATURE Wayne	works	TITLE Agent		DATE 06-26-00		
TYPE OR PRINT NAME Wayne Brooks				TELEPHONE NO. 915-580-71	61	
(This space for State Use)				122 11012110. 0 10 0007/1	<del></del>	
,						
_						
APPROVED BY Miles Stellfull		TITLE FIELD 1	<b>^</b>	DATE 6/30/7000		