## 10. PLAN FOR RESTORATION OF SURFACE

All pits will be filled in and leveled. Deadmen will be removed. The access road and location will be restored as near as possible to its natural state following instructions from appropriate governmental agency, if well is abandoned, otherwise the location will be cleared and maintained in an orderly manner.

## 11. OTHER INFORMATION No unusual topography exists on the well site or access roads.

## 12. OPERATOR REPRESENTATIVES

Paul Ragsdale P.O. Drawer 730, Roswell, New Mexico 88201 622-3200

## 13. CERTIFICATION

I certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed by New Mexico Institute of Mining and Technology and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved.

Lagradal .... au Paul Ragsdale

Agent