

X-Pert Well Service, Inc.

OIL WELL SERVICING

CARLSBAD HIGHWAY, WEST

POST OFFICE BOX 1225
HOBBS, NEW MEXICO

TELEPHONE EXPRESS 3-9171

September 19, 1960

RECEIVED

SEP 26 1960

O. O. O.
ARTESIA, OFFICE

Mr. M. L. Armstrong
321 Carper Building
Artesia, New Mexico

Re: Morris Estate Well #1
L-14-17-25 Eddy Co., N.M.

Dear Mr. Armstrong:

Enclosed, please find the following forms:

1. C-103 on Surface Pipe.
2. C-103 on Liner
3. ~~C-105~~ Well Log
4. C-110 Authority to Transport
5. C-126 Load Oil
6. Radio activity log

You requested that we inform you as to the present status of the well. This is to advise you that the well is presently producing at 3 BOPD and 1 Bbl. water per day when produced. Since the load was so long in coming back, the pumper was unaware that the well was on new production and contacted purchaser without our knowledge to move the new oil. The purchaser ran 332 Bbls. of new oil. It was our intention to test this well for an extended period before making a potential, and it was our opinion that the tank room was adequate to handle this small amount of oil.

Please accept our apology for this oversight and wish to advise you that this will not happen again.

Yours very truly,



M. S. Thompson,
Operator