casing is deep enough to shut off all of the Artesian zone and the one plug at 2475' is below the top of the Glorietta section which probably accounts for the sulfur water.

I inspected this well on Friday, October 1, and found the fluid level at approximately 25° from surface. Also, a string of 6 5/8" casing has been run in the well and welded to a swedge nipple from the 9 5/8" surface casing with a 6" gate valve installed which was open. Also, the circulating and reserve pits were not filled and leveled.

Yours very truly,

L. A. HANSON Supervisor, 011 & Gas Inspector

LAH/1h

casing to map arough the arms off who as the Letimatian vous and If a one ploy at \$4758 is ballow as a registric within Elementic accide whole probably avacents for the publics werary

1 it is acted this well on truck, the of us 2, and tound to find the start of approximating for the main of a line, a string of a p/AM usaing the best in the start of and and the a string minple from the 9 f/M antions can be done with a 50 force whether which has open. Along the of weighting are receive why here using fifthet we hereled.

, dinis a se se al

1. i. i.k. 1917) Serrer mineter, 1948 i mas In**asynoso**rg