



TEMPERATURE SURVEY

Location 660 FROM NORTH 1980 FROM EAST SEC. 30 TWP. 16-S RGE. 26-E	COMPANY <u>DE KALB AGRICULTURAL</u>		COMPANY DE KALB AGRICULTURAL ASSOCIATION <u>FILE</u> WELL <u>SHUGGART # 1</u> FIELD <u>WILDCAT</u> County <u>EDDY</u> State <u>NEW MEXICO</u> Sec. <u>30</u> Twp <u>16-S</u> Rge <u>26-E</u> Survey _____
	ASSOCIATION <u>FILE</u>		
	WELL <u>SHUGGART # 1</u>		
	FIELD <u>WILDCAT</u>		
	County <u>EDDY</u> State <u>NEW MEXICO</u>		
Sec. <u>30</u> Twp <u>16-S</u> Rge <u>26-E</u>		Survey _____	
Log Measured From <u>TOP DRIVE BUSHING</u> Elevation _____			
Drilling Measured From <u>TOP DRIVE BUSHING</u> Elevation _____			
Permanent Datum <u>GROUND LEVEL</u> Elevation _____			
Date of Cementing <u>4-9-53</u> Time <u>2:00 P. M.</u>			
Date of Survey <u>4-10-53</u> Time <u>12:01 A. M.</u>			
Amount of Cement <u>300 SACKS</u> Type <u>6% GEL</u>			
Amount of Admix _____ Type _____			
Casing Size	Casing Depth	Diam. of Hole	Depth
<u>13 3/8"</u> from <u>0</u> to <u>120</u>	<u>17 1/2"</u> from <u>0</u> to <u>120</u>	<u>8 5/8"</u> from <u>0</u> to <u>1082</u>	<u>12"</u> from <u>120</u> to <u>1082</u>
from _____ to _____	from _____ to _____	from _____ to _____	from _____ to _____
from _____ to _____	from _____ to _____	from _____ to _____	from _____ to _____
Survey Begins at <u>10</u> Ft. Ends at <u>1040</u> Ft.			
Bottom Hole Temp. <u>75</u> °F Max. Temp. <u>75</u> °F			
Run No. <u>ONE</u> Approx. Top Cement <u>40</u> Ft.			
Recorded by <u>J. D. FULCHER</u> Witnessed by <u>J. B. SHADDEN</u>			
REMARKS OR OTHER DATA			
----- NOT AVAILABLE			
TEMPERATURE IN DEGREES FAHRENHEIT			

