

[illegible]

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

MAILED
 35-2 1934

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned
500 gal	acid					
1000 gal	acit					

D. E. C.
 SURVEYING OFFICE

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from 0 feet to 492 feet, and from _____ feet to _____ feet

DATES

_____, 19____ Put to producing 12-19-_____, 1949

The production for the first 24 hours was 25 barrels of fluid of which 100 % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé _____

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____
 Rock pressure, lbs. per sq. in. _____

EMPLOYEES

B. J. Rogers _____, Driller _____, Driller
 Carl Byler _____, Driller _____, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	2	2	Calechie
2	25	23	Red bed
25-	80	55	Red bed and lime shells
80	145	65	Anhydrite
145	158	13	Blue shale
158	260	102	Red bed and Anhydrite
260	270	10	Anhydrite
270	285	15	Red bed & shells
285	304	19	Red bed & shells
304	325	21	Anhydrite broken
325	332	7	Lime brown
332	395	62	Anhydrite
395	400	5	Lime
400	435	35	Anhydrite
435	437	2	Red and Anhydrite
437	441	4	lime
441	445	4	Brown lime
445	461	6	Anhydrite
461	463	2	Brown lime first free oil
463	477	14	anhydrite
477	480	3	brown lime showing of free oil
480	485	5	anhydrite
485	487	2	brown lime
487	492		anhydrite