

NOTICE OF INTENTION TO ABANDON WELL	WATER CASING	OF ABANDONMENT	SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 18, 1950

Well No. (1-A) is located 1650 ft. from [N] line and 990 ft. from [E] line of sec. 13
13 (1/4 Sec. and Sec. No.) 17 S. 27 E. (Twp.) N.M.P.M. (Meridian)
Empire (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pumped 15 sacks cement through tubing, Denton cementing method, from bottom of hole, 492 feet up to within the 5 1/2" pipe, 150', ~~knocked off~~ set plug, knocked off 200 feet of pipe and pulled, continued to fill hole with heavy mud, and set regulation marker, cleaned location.

Let cement set 72 hours, tested to see if hole was dry, and found it dry, before setting plug and pulling pipe.

U. S. GEOLOGICAL SURVEY
 RECEIVED
 AUG 21 1950
 ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ray Hightower
 Address 812 West Main
Artesia, New Mexico
 By Mrs Ray Hightower
 Title _____

RECEIVED
 SEP 2 1950
 D.C.F.
 ARTESIA, N.M.