

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUN 22 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator C. E. LaRue and B. N. Mumcy, Jr.	5. State Oil & Gas Lease No. E 3060
3. Address of Operator P. O. Box 196, Artesia, New Mexico 88210	7. Unit Agreement Name
4. Location of Well UNIT LETTER I 1650 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 17S RANGE 27E N.M.P.M.	8. Form or Lease Name Collier N
	9. Well No. 1
	10. Field and Pool, or Wildcat Empire (Y,SR)
15. Elevation (Show whether DE, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug well as follows: TD 437 7" 420-255X

1. Set 100' cement plug at TD.
2. Cut off and pull casing at 300'.
3. Set 100' Cement plug at casing cut off point.
4. Set 10 Sack cement plug at surface.
5. Heavy mud between all plugs.
6. Set Dry hole marker.
7. Clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operator DATE June 10, 1976

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 22 1976

CONDITIONS OF APPROVAL, IF ANY: 20 sack surface plug Notify N.M.O.C.C. in sufficient time to witness [Signature]