

Operator C E LaRue
 Well Collier 'C' STATE #1
 Unit 3 Section 12 Township 17 Range 27
 API # 30-015-CCSSC

TOPS

Water 58-75'
Water 165-170'
Oil Show - 420-430'

← 60' Surface Plug.

- * Contact OCD 24 hrs. prior to any work done.
- * Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- * Install dry hole marker as per Rule 202.B.2
- * Plugs are to be set from point indicated up.
- * Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- * Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- * Surface plug will be from 0' - 60'
- * Where plugs are required, cement must be placed inside and outside of **all** casing string(s) in the correct footage or sacks required, if **no cement exists**.
- * Plugs to be tagged will be indicated.

Toe ——— 181' @ 75%
 ———

7" @ 420'
 w/ 25 SACS CMT

← 420' Shoe Plug. TAG

TD 432'