

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TR
(Other instructio
verse side)

DATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NY-C557370

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
GEORGE L. SHADE

3. ADDRESS OF OPERATOR
P. O. BOX 637, ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Sec. 26, T. 17S, R. 27E, Sully County,
New Mexico (330' / s and 990' / s)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH
SULLY

13. STATE
NEW MEXICO

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
HUNDA

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
RED LARK

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 26 T. 17S R. 27E

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

To 1280' (i. e. 160' / s, 3-1/2" casing set at 1280' with 30 sacks of cement.

We intend to:

set packer and check water in the formation at 1565', or Premier pay; if no formation water, set 4-1/2" liner 1150' - 1565' with 30 sacks of cement. Perforate Penrose, gas sand at 1100' and frac at same time; will not perforate Premier; will not perforate liner; shoe of liner at 1565'. Will commingle the Penrose and Premier zones. Set pipe on top of pay at 1560'.

To use 750 barrels water and oil at each zone and coarse sand as necessary, or as Cowell recommends, as well as approximately 200 gallons of acid - 100 per zone.

Propose to sell gas to Phillips Petroleum Company, photo of letter from that company dated 2-6-68, by William L. Ware, attached.

RECEIVED
FEB 12 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED George L. Shade TITLE Owner DATE 2-12-68

(This space for Federal or State office use)

APPROVED BY R. L. Buchanan TITLE Geologist DATE 2-12-68
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
FEB 13 1968
R. L. BUCHANAN
ACTING DIRECTOR

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED
JUN 1964