

Operator Mason Phillips Properties
 Well S. Red Lake Grayburg Unit #24
 Unit I Section 35 Township 17 Range 27
 API # 30-015-00622

TOPS

Yates ~ 480
Powers ~ 850
Queen ~ 1015
Grayburg ~ 1450

← Surface Plug
 0' - 60'

← Plug 480'
 Perf. + 5002.

— TOC 904'

- * Contact OCD 24 hrs. prior to any work done.
- * Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- * Install dry hole marker as per Rule 202.B.2
- * Plugs are to be set from point indicated up.
- * Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- * Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- * Surface plug will be from 0' - 60'
- * Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists.
- * Plugs to be tagged will be indicated.

← Plug 1496' TAG

7" @ 1496
 100 SXS.
 1

TIN 1741

[Signature]