

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Copy to SF
Form approved
Budget Bureau No. 49-R1434

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL ☒ GAS ☐ OTHER ☐

1. NAME OF OPERATOR
Cities Service Oil Company

2. ADDRESS OF OPERATOR
Box 1919, Midland, Texas 79701

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
990' FSL & 1650' FEL
Section 35-T17S-R27E
Eddy County, New Mexico

14. PERMIT NO.

15. ILLUSTRATIONS (Show whether SP, ST, OR, etc.)

RECEIVED

FEB 9 1977

O. C. C.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
LC 028755 (A)

6. IF INDIAN, ALLOTTEE OR TRUST NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Russell C

9. WELL NO.
5

10. FIELD AND TOWN, OR WILDCAT
Empire Yates - 7 Rivers

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA
Sec. 35-T17S-R27E

12. COUNTY OR PARISH 13. STATE
Eddy New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FULL OR ALTERNATE CLOSING

FRACURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERNATE CLOSING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recommendation Report and Log form.)

17. DESCRIBE IN BRIEF OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and notes pertinent to this work.)

TO 476' Line, 8" casing @ 402'. We propose to plug and abandon this well in the following manner:

1. MIRM pulling unit. POOH with rods and tubing.
2. RIM with open ended tubing.
3. Circulate hole with 130 sacks cement 476-0'. (Estimated top of cement behind 8" casing is 250').
4. POOH with tubing and install 4" dry hole marker.

RECEIVED

NOV 19 1976

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Elmer Stutz

TITLE

Region Petroleum Engineer

DATE November 18, 1976

(This space for Federal or State office use)

APPROVED BY

Joe D. Lamm

TITLE

ACTING DISTRICT ENGINEER

DATE

FEB 8 1977

CONDITIONS OF APPROVAL, IF ANY: