

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dsf
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 2029-21
7. Lease Name or Unit Agreement Name
State
8. Well No. 1
9. Pool name or Wildcat Vandagriff Keyes Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED SEP 24 1991 O. C. D. ARTESIA OFFICE
2. Name of Operator Marbob Energy Corporation ✓	
3. Address of Operator P. O. Drawer 217, Artesia, NM 82810	
4. Well Location Unit Letter <u>P</u> : <u>330</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon as follows: Set cmt plug from PBTD to 1100'. Tag plug @ 1190'. Set cmt plug from 700-500'. Set surface plug. Install dry hole marker and clean location.

* Perf @ 300' & circ.
gel between plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robin Smith TITLE Production Clerk DATE 9/20/91
TYPE OR PRINT NAME Robin Smith TELEPHONE NO. 748-3303

(This space for State Use) * As noted above

APPROVED BY Johnny Robinson TITLE Oil and Gas Inspector DATE 10-1-91
CONDITIONS OF APPROVAL, IF ANY:

Plugging