



P. O. Box 55

Address Artesia, New Mexico

Field Artesia State New Mexico

Location 325 ft.  $\left\{ \begin{smallmatrix} \text{N.} \\ \text{S.} \end{smallmatrix} \right\}$  of 5 Line and 160 ft.  $\left\{ \begin{smallmatrix} \text{E.} \\ \text{W.} \end{smallmatrix} \right\}$  of C Line of 18 Elevation 366  
(Derrik floor relative to sea level)

Signed George C. Bobb  
Title Genl mgr.

Title Gent. m. g.

Commenced drilling September, 1925, 19\_\_\_\_ Finished drilling Dec. 23, 1925, 19\_\_\_\_

(Denote gas by  $G$ )

No. 2, from ..... to ..... No. 5, from ..... to .....

No. 3, from \_\_\_\_\_ to \_\_\_\_\_ No. 6, from \_\_\_\_\_ to \_\_\_\_\_

No. 1, from 240 to 251 **IMPORTANT WATER SANDS** No. 3, from \_\_\_\_\_ to \_\_\_\_\_

No. 2, from \_\_\_\_\_ to \_\_\_\_\_ No. 4, from \_\_\_\_\_ to \_\_\_\_\_

### CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From	To	
6 3/8	18			621					
-3/16				621					
HISTOBA ON ONT OF CTS UNIT									
Q-2192									

### MUDDING AND CEMENTING RECORD

[illegible]

## PLUGS AND ADAPTERS

Heaving plug—Material ..... Length ..... Depth set .....

**Adapters—Material** ..... **Size** .....

## SHOOTING RECORD

[illegible]

## TOOLS USED

Rotary tools were used from Cable feet to 0 feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet

Cable tools were used from \_\_\_\_\_ feet to \_\_\_\_\_ feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet

## DATES

Put to producing Jan 10, 1926

barrels of fluid of which 100 % was oil. 0 %