3160-5	UNITED STATES DEPARTMENT OF THE INTERIOR		N.M. Oil Consi Division Order APPROVED 811 S. 1st Street Expires November 30, 2000	
ust 1999)	BUREAU OF LAND MAN	AGEMENT		88212-283449A
0.00	NUNTICES AND REP	ORTS ON WEL	13	
Do not use abandoned	this form for proposals to well. Use Form 3160-3 (AP	o drill or to re-e PD) for such prop	posais.	6. If Indian, Allotice or Tribe Name
SUBMITIN	HIPLICATE - Other Inst	ructions on rev	versa side	7. If Unit or CA/Agreement, Name and/or No.
Type of Well Oil Well Gas Well				8. Well Name and No. Brooks # 17.
Name of Operator	/			9. API Well No.
JDR Ltd		3b. Phone No.	(include area code)	30-015-01433
Address	tesia NM 88210	505-748	3-2134	10. Field and Pool, or Exploratory Area
Location of Well (Footage,	Sec., T., R., M., or Survey Description	on)		Empire Y-SR 11. County or Parish, State
	1734 W 19-17-27			Eddy NM
12. CHECK	APPROPRIATE BOX(ES)	TO INDICATE N	NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION	
		Deepen	—	Start/Resume) 🖸 Water Shut-Off
Notice of Intent	Alier Casing	Fracture Tres		— • • •
	Casing Repair	New Constru		
Subsequent Report	Change Plans	Plug and Aba	andon [] Temporaniy	A08/100/1
	1			
Attach the Bond under white following completion of the	E Convert to Injection leted Operation (clearly state all pe directionally or recomplete horizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall		ding estimated starting date e locations and measured an on file with BLM/BIA. R	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da then in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed. determined that the site is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete horizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.)	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zond equired subsequent reports shall be filed within 30 da then in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed. determined that the site is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	of any proposed work and approximate duration thered d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry .ectric line \$s
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da then in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry .ectric line \$s
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	of any proposed work and approximate duration thered d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry .ectric line \$s
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe directionally or recomplete horizon the work will be performed or p involved operations. If the operat Final Abadonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an for other Wells.	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry .ectric line \$s
Describe Proposed of Comp If the proposal is to deepen Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an for other Wells.	trinent details, includ traily, give subsurface provide the Bond No. idon results in a multip i be filed only after a d Tubing, id reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, focluding	of any proposed work and approximate duration thered d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry .ectric line \$s
Describe Proposed or Comp If the proposal is to deepeo Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an for other Wells.	ertinent details, includ taily, give subsurface provide the Bond No. in results in a multi to filed only after a nd reclame	Water Dispo ding estimated starting date e locations and measured and on file with BLM/BIA. R ple completion or recomple all requirements, including fill with Rea location. El	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Porm 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line ±s
Describe Proposed or Comp If the proposal is to deepeo Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe directionally or recomplete borizon the work will be performed or p involved operations. If the operat Final Abandonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker an for other Wells.	ertinent details, includ taily, give subsurface provide the Bond No. in results in a multi to filed only after a nd reclame	Water Dispo ding estimated starting date e locations and measured and on file with BLM/BIA. R ple completion or recomple all requirements, including fill with Rea location. El	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da thon in a new interval, a Porm 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line ±s
Describe Proposed or Comp If the proposal is to deepeo Attach the Bond under whit following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe- directionally or recomplete horizon the work will be performed or p- involved operations. If the operat Final Abadonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker and for other Wells. wid intro- going is true and correct on Bell HAMM	ertinent details, includ taily, give subsurface provide the Bond No. ind reclame d Tubing, nd reclame	Water Dispo ding estimated starting date e locations and measured and on file with BLM/BIA. R ple completion or recomple all requirements, locluding fill with Real location. Ell Tiute Agen Date 1-22-01	sal of any proposed work and approximate duration there d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da tion in a new interval, a Porm 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line ±s t t
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under white following completion of the testing has been completed, determined that the sile is re Plan to to used	Convert to Injection leted Operation (clearly state all pe- directionally or recomplete horizon the work will be performed or p- involved operations. If the operat Final Abadonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker and for other Wells. wid intro- going is true and correct on Bell HAMM	ertinent details, includ taily, give subsurface provide the Bond No. ind reclame d Tubing, nd reclame	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, including fill with Rea location. El Title Agen	sal of any proposed work and approximate duration thered d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da tion in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line \$s ACCUSE ACCUSE T
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under which following completion of the testing has been completed, determined that the sile is re- Plan to to used	Convert to Injection leted Operation (clearly state all pe- directionally or recomplete borizon the work will be performed or p- involved operations. If the operat Final Abadonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker and for other Wells. for other Wells. on Bell	ertinent details, includ taily, give subsurface provide the Bond No. ion results in a multi- il be filed only after a nd reclame EFOR FEDERAL K	Water Dispo ding estimated starting date e locations and measured and on file with BLM/BIA. R ple completion or recomple all requirements, locluding fill with Real location. El Title Agen Date 1-22-01 COR STATE OFFICE Title	sal of any proposed work and approximate duration thered d true vertical depths of all pertinent markers and zone equired subsequent reports shall be filed within 30 da tion in a new interval, a Porm 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line ±s t t
Describe Proposed or Comp If the proposal is to deepen Attach the Bond under which following completion of the testing has been completed, determined that the sile is re- Plan to to used	Convert to Injection leted Operation (clearly state all pe- directionally or recomplete horizon the work will be performed or p- involved operations. If the operat Final Abadonment Notices shall ady for final inspection.) to pull Rods and p. Set Marker and for other Wells. Soing is true and correct on Bell How IG SGD.) LES BABYA are stached. Approval of this mail is to conduct operations thereon.	ertinent details, includ taily, give subsurface provide the Bond No. iton results in a multi if be filed only after a a Tubing, a Tubing, a Teclame FOR FEDERAL K otice does not warrant ights in the subject 1	Water Dispo ding estimated starting date e locations and measured an on file with BLM/BIA. R ple completion or recomple all requirements, including fill with Rea location. El Title Agen Date 1-22-01 COR STATE OFFICE Title N or lease Office	sal of any proposed work and approximate duration thered d true vertical depuls of all pertinent markers and zone equired subsequent reports shall be filed within 30 da then in a new interval, a Form 3160-4 shall be filed on reclamation, have been completed, and the operator h ady mix slurry ectric line ±s t USE J/16/01