

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ Injection O. C. D. ARTESIA OFFICE
2. NAME OF OPERATOR
Kersey & Company
3. ADDRESS OF OPERATOR
P.O. Box 316, Artesia, NM 88211-0316
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE:
AT TOP PROD. INTERVAL: 1650/N
AT TOTAL DEPTH: 1980-E
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- | | | |
|----------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| (other) | <input type="checkbox"/> | <input type="checkbox"/> |

5. LEASE
LC-065729
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
RLPSU Flood
8. FARM OR LEASE NAME
RLPSU - Tract 12
9. WELL NO.
3 (Welch Reid)
10. FIELD OR WILDCAT NAME
Red Lake-Q-G-SA
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit G
1650 N, 1980 E, Sec. 20-17-28
12. COUNTY OR PARISH Eddy 13. STATE NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 25 sacks plug at 1590 → 1950'
- Casing perforated at 1000'
- 15 sacks plug back to 900'
- Casing perforated at 650';
- Cement plug back to 306'
- Surface plug 10 sacks
- Marker

RECEIVED
NOV 20 1 20 PM '87
CARLOS J. SANCHEZ
AREA HEADQUARTERS

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Harold Kersey TITLE Co-Owner DATE 11-19-87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Post FD-2
12-11-87
PxA