

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8435

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection	<div style="border: 2px solid black; padding: 5px; transform: rotate(-5deg);"> RECEIVED BY DEC 17 1985 O. C. D. ARTESIA, OFFICE </div>	7. Unit Agreement Name Red Lake Premier Sd. Unit
2. Name of Operator Kersey & Company		8. Farm or Lease Name Scannett Tr 6
3. Address of Operator P.O. Box 316, Artesia, NM 88210		9. Well No. 2
4. Location of Well UNIT LETTER P 330 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 17S RANGE 23E NMPM.		10. Field and Pool, or Wildcat Red Lake
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Put cement plug 1930-1700'  
Tag top plug 1700'
- Put cement plug 1100'-870'  
Tag top plug at 870'
- Put Cement plug 575'-339'  
Tag top plug at 339'
- Put cement plug at 30'-surface.
- Install 4" pipe marker at surface

Post FD-2  
1-17-86  
P x A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harold Kersey</u>	TITLE <u>Co-Owner</u>	DATE <u>12-16-85</u>
APPROVED BY <u>Danell Moore</u>	TITLE <u>Geologist</u>	DATE <u>4/10/86</u>
CONDITIONS OF APPROVAL, IF ANY:		