

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
MAR 18 1992

WELL API NO. 30-015-01538
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "C"
8. Well No. 43
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ARCO OIL AND GAS COMPANY	
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88241-1710	
4. Well Location Unit Letter J : 1650 Feet From The SOUTH Line and 1980 Feet From The EAST Line Section 25 Township 17S Range 28E NMPM EDDY County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3694' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

HOLD WELL BORE TO MONITOR BHP

TD 6380'; PBD 6216'; PERFS: 6200-08'; PKR 6176.82'

2/28/92 RUN PKR TO TA WELL. PUMP 75 BBLS PKR FLUID, SET PKR w/11000# COMPRESSION, LOAD AND PRESSURE CSG TO 560#, HELD FOR 15 MINS. TEST CHART ATTACHED.
WITNESSED BY GARY WILLIAMS, NMOCD.

2/97

G.W.
NMOCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Operations Coordinator DATE 3/16/92
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 391-1600

(This space for State Use)

APPROVED BY G. Williams TITLE Field Rep DATE 3/25/92
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 18 1992

O. C. D.
SPECIAL OFFICE

