

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>647</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Convert to SWD Well</b>	7. Unit Agreement Name
2. Name of Operator <b>Hondo International Gas Company</b>	8. Farm or Lease Name <b>State "A"</b>
3. Address of Operator <b>P. O. Box 1978, Roswell, New Mexico 88201</b>	9. Well No. <b>45</b>
4. Location of Well UNIT LETTER <b>G</b> <b>2310</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>26</b> TOWNSHIP <b>17-S</b> RANGE <b>28-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Empire-Abo</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3664' Ground</b>	12. County <b>Eddy</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <b>Convert to SWD Well</b> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Temporarily abandoned Abo perfs in this well by setting a Baker CIBP @ 4158' WLM. Capped plug w/4 sx of cement placed w/dump bailer. Top of cement at 4108'. Perforated 2649-50 w/4 jets. Block squeezed these perfs w/10 sx Class "C" cement @ 3700#. WOC 20 hours. Drilled out cement and tested squeeze job to 2000#. Held OK. Perforated Paddock zone 3809-49, 3928-40 and 4000-30, w/2 JSPF. Treated w/5000 gal. 15% HCl acid. AIR = 6.7 BPM @ 2100#. On 24 hr injection test, pumped in 1206 bbls water at 1050#. Ran 2-3/8" J-55 tubing (plastic coated internally w/TK-90) and Halco R-3 packer. Set packer at 3742'. Well is now salt water disposal well.

**RECEIVED**  
**DEC 10 1968**  
**O. C. C.**  
**ARTERIA, OFFICE**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **O. D. Bretches** TITLE **Dist. Drilling Supervisor** DATE **12-9-68**

APPROVED BY **W. A. Gressett** TITLE **OIL AND GAS INSPECTOR** DATE **12-10-68**  
CONDITIONS OF APPROVAL, IF ANY: