

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.S.	☒
LAND OFFICE	☒
OPERATOR	☒

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. 647	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER- SWDW		7. Unit Agreement Name E.A. Press. Maint. Project
2. Name of Operator ARCO Oil and Gas Company, Division of Atlantic Richfield Company		8. Farm or Lease Name Empire Abo Unit "B"
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 39
4. Location of Well UNIT LETTER G 2310 FEET FROM THE ^{NORTH} SOUTH LINE AND 1980 FEET FROM THE East LINE, SECTION 26 TOWNSHIP 17S RANGE 28E NMPM.		10. Field and Pool, or Wildcat Swk. Part of the Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3664' GR		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up on 10/11/82. Installed BOP. Rel pkr & POH. Drld & CO to 6223'. Set cmt retr @ 6073'. Cmt sqzd Abo perfs 6127-6220' w/200 sx C1"C" cmt on vac. Cleared cmt, WOC 4 hrs. Sqz cmt thru retr @ 6073' w/150 sx C1"C". Final press. 1200#. Dumped 50' cmt on top of retr. Set pkr @ 3650', press annulus to 1000# for 30 mins. OK. POH w/pkr. Set cmt retr @ 3649'. Sqz cmt perfs 3809-4030' w/150 sx C1"C" neat cmt. Final sqz press 1500#. Dumped 50' cmt on top of retr. Circ 10# brine wtr to 900'. Spot C1"C" cmt plug 900-600'. WOC. Tagged cmt plug w/tbg @ 578'. OK. Spot C1"C" cmt plug 156' to surf. Cut off wellhead below ground level. Install regulation dry hole marker. Clean and level location. P&A eff: 10/19/82. Final Report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth L. Bush TITLE Drlg. Engr. DATE 10/21/82

APPROVED BY Larry Brooks TITLE Geologist DATE 3/17/83

CONDITIONS OF APPROVAL, IF ANY: