

FIELD TRIP REPORT

L A S S I F A C I T I O N A T I O N	Q U A R T E R H O U R S	Name <u>Gary Williams</u>	Date <u>7/25/90</u>	Miles <u>76</u>	District <u>II</u>
		Time of Departure <u>7:30 Am.</u>	Time of Return <u>4:00 PM</u>	Car No. <u>11239</u>	
In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.					
Signature _____					
0072	<p>1- Well 25-17-28 Kersey Welch #12 well plugged with 4½ yds of ready mix to surface - 650 ft to surface</p> <p>CK T+As in start + general injection of area</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>				
	<u>Mileage</u> UIC _____ RFA _____ Other <u>76</u>				
	<u>Per Diem</u> UIC _____ RFA _____ Other _____				
	<u>Hours</u> UIC _____ RFA _____ Other <u>7½</u>				

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
I - Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry	D = Drilling
P - Plugging	Injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	P = Production
C - Plugging Cleanup	R = Inspections relating to Reclamation Fund Activity	I = Injection
T - Well Test	O = Other - Inspections not related to injection or The Reclamation Fund	C = Combined prod. inj. operations
R - Repair/Workover	E = Indicates some form of enforcement action taken in the field (allow immediately below the letter E) P = O	S = SWD
F - Waterflow		U = Underground Storage
M - Mishap or Spill		G = General Operation
W - Water Contamination		F = Facility or location
O - Other		H = Menting
		O = Other