

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 4 1972

O. C. C.
ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
647	
7. Unit Agreement Name	
8. Farm or Lease Name	
M. Yates	
9. Well No.	
6	
10. Field and Pool, or Wildcat	
Artesia	
12. County	
Eddy	

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Atlantic Richfield Company ✓
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER <u>L</u> , <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>17-S</u> RANGE <u>28-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3668' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned in the following manner:

Displaced 30 sx Class H cement to 1386', plugged across zone 1400-1625'. Shot off 5½" casing @ 1259'. Pld 41 jts 5½" casing. Spotted 30 sk cement plug 1320-1122', 30 sack cement plug 720-620' over 8-5/8" casing shoe @ 680'. Set 10 sk cement plug in surface. Erected dry hole marker. 9#/gal gel mud was left between all cement plugs. 8-5/8" casing remains intact. Well P & A 1/29/72.

Your office will be notified when this location is ready for inspection.

*dry hole - 8 5/8" - 680' - circ.
5 1/2" from 1251 - 2143*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O.D. Sretches TITLE Dist. Drlg. Supervisor DATE 2/2/72

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE MAR 13 1973

CONDITIONS OF APPROVAL, IF ANY: