Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department



Form C-103 Revised 1-1-89

District Office		•	V .	Action 1-1-07
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATION DIVISION 2040 Pacheco St.		WELL API NO.	06
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505		30-015-016 5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STA' 6. State Oil & Gas Lease No	TE X FEE
			VIIII III III III III III III III III I	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Empire Abo Unit "H"		
1. Type of Well: OIL GAS WELL X WELL	OTHER			
2. Name of Operator V				
ARCO Permian			32	
3. Address of Operator P.O. Box 1089 Eunice, NM 8	8231		9. Pool name or Wildcat Empire Abo	
4. Well Location Unit Letter P : 990	Feet From TheS	Line and 66	Feet From The	ELine
Section 33	Township 17S	Range 28E	NMPM Eddy	County
		ther DF, RKB, RT, GR, etc 3661 GR		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERIN	ig casing
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING		ND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Ope	rations (Clearly state all pertinent d	letails, and give pertinent da	tes, including estimated date (of starting any proposed
work) SEE RULE 1103.				
TD: 6345' PBD: 5948'	(CIBP) PERFS: 5972-6010),		
08/19/97: Load w/20 bbls 8# brine. Press up to 700#, leaked off. 08/20/97: Tag CR @ 6200'. POH, set pkr. Test CR to 800#, held good. POH setting pkr to locate hole in csg. Located leak off @ 6041-6074'.				
08/20/97: Tag CR @ 6200'. POH. set pkr. Test CR to 800#, held good. POH setting pkr to locate hole in csg. Located leak off @ 6041-6074'.				
08/21/97: RIH w/CIBP. Set @ 6020'. Load hole, press to 600#, held good.				
08/22/97: Perf upper abo w/1-11/16" 5972-6010', 2 JSPF, 73 holes.				
08/25/97: Acidize w/12000 gals 15% NEFE charged w/36,000 SCR N2. Max 4200#, Min 750#.				
Avg 2475# @ 2 BPM. ISIP 2360#. Ran 80 ball sealers. Good ball action.				
08/29/97: Circ well w/65 bbls 8.6# brine w/pkr fluid. Close in BOP, press to 480#, held				
20 mins. Pre	ss test chart attached.	Workover unsuccessf	ul. Well currently	TAS SSISS PAT
Avg 2475# @ 2 BPM. ISIP 2360#. Ran 80 ball sealers. Good ball action. 08/28/97: RIH w/4-1/2" CIBP and tag. Set CIBP @ 5948". 08/29/97: Circ well w/65 bbls 8.6# brine w/pkr fluid. Close in BOP, press to 480#, held 20 mins. Press test chart attached. Workover unsuccessful. Well currently TA 2.222000000000000000000000000000000000				
SIGNATURE THE Administrative Assistant DATE 05/11/99				
TYPE OR PRINT NAME Kellie D. MUD	rish		TELEPHONE	E NO. 505-394-1649
(This space for State Use)		1 1 10		

This Approval of Ter Abandonment Expires LAR 1333
Co Secretaria Recorded Recorde