

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR REEQUIP A WELL IN A RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR TO REOPEN OR REEQUIP A WELL FOR SUCH PURPOSES.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
C. E. LaRue and B. N. Muncy, Jr.

3. Address of Operator
P.O. Box 196, Artesia, New Mexico 88210

4. Location of Well
UNIT LETTER H 1650 FEET FROM THE North LINE AND 330 FEET FROM
THE East LINE, SECTION 34 TOWNSHIP 17S RANGE 28E N.M.P.M.

5. Elevation (Show whether DF, RT, GR, etc.)

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
E 2071

7. Unit Agreement Name

6. Name of Lease Name
Moore State

9. Well No.
1

10. Field and Pool, or Without Artesia (Q, G, SA)

12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon by pumping 25 sack cement plug @ 2250', cut off and pull approximately 1400' of 5-1/2" casing, pump 35 sack cement plug at cut-off point, pump 35 sack cement plug at 900', pump 50 sack cement plug from 400'-550', 10 sack cement plug at surface with heavy mud between all plugs. Set dry hole marker and clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operator DATE June 19, 1973

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 27 1973

CONDITIONS OF APPROVAL, IF ANY: