

8-10-61

Mr. Welch called + wanted oral o.k.
on plugging, as they were ready to go.
said he would send in the Balance of
required papers on this well, along with
plugging report. Said there were no shows
of gas + oil in this well, but some air at
1800'. 430' of 8 $\frac{5}{8}$ " surface with
50 sks. will load hole with mud
before plugging

will plug as follows.

1. plug at 1800'
2. plug below 8 $\frac{5}{8}$ "
3. plug at stub of 8 $\frac{5}{8}$ " cut off
at top cement.

H. h.