

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP 13 '90

WELL API NO. 30-015-01736
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 38
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240

4. Well Location Unit Letter <u>C</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>35</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3684' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	TEMPORARILY ABANDON- <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD - 6345'; PBD - 6310'; Perfs: 6208-6222'

9/07/90 MIRU DDP. Well dead. N/D W/H N/U BOP. Unset pkr. Pickup 2 jts tbg. GIH to top of perfs. POH w/tbg, S.N. and pkr. SDON.

9/08/90 R.O. Well dead. GIH w/5-1/2" CIBP, running tool, S.N. and tbg. Set CIBP @ 6187.24' (w/KB). POA w/1 jt tbg. R/U Kill Truck. Circulate well w/105 bbls 8.6# brine w/WT-675 chemical. Shut well in. Pressure up to 500 psi. Held for 20 mins. No loss in pressure. R/D Kill Truck. POH w/tbg, S.N., and running tool, laying down in singles. N/O BOP N/U W/H. Left 1 jt tbg on W/H flange. RDCL. CIBP set @ 6187.24' RKB. Pressure test chart attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James B. Cogburn TITLE Administrative Supervisor DATE 9/12/90
TYPE OR PRINT NAME James B. Cogburn TELEPHONE NO. 392-3551

(This space for State Use)

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE 9/20/90
CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 9/8/95