

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 29 12 46 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	647

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hondo-International-Yates	8. Farm or Lease Name State "A"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201	9. Well No. 39
4. Location of Well UNIT LETTER K 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 17-S RANGE 28-E NMPM.	10. Field and Pool, or Wildcat Empire-Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3688' DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER Recomplete in Upper Abo <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Water production has increased to a point where it is necessary to swab the well several times per month to maintain flow. We propose to temporarily abandon Abo perforations 6297-6308' with a CIBP set @ 6280'; perforate Abo 6243-6258 w/2 JSPP and treat w/2000 gal 15% HCl acid. Completion assembly will be 2" tubing w/tension packer set @ about 6175'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **O. D. Bretches** TITLE **Dist. Drlg. Supervisor** DATE **5-28-69**

APPROVED BY **W. A. Gressett** TITLE **OIL AND GAS INSPECTOR** DATE **JUN 2 1969**

CONDITIONS OF APPROVAL, IF ANY: