

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised March 25, 1999

WELL API NO.
30-015-01752

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Empire ABO Unit "F"

8. Well No.

F-37

9. Pool name or Wildcat

ABO

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator BP America /

3. Address of Operator P.O. BOX 1089 Eunice, New Mexico

4. Well Location

Unit Letter _____ : 1850 feet from the North line and 710 feet from the West line

Section ~~17S~~ 35 Township ~~28E~~ 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
KB 11' AGL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-11-02 Tag CIBP @ 6207' Circulate Hole Salt gel Mud. Spot 25 sx Class C 6207'-5956'.

9-18-02 Spot 25 sx Class C 3710'-3610.

9-20-02 Spot 35 sx Class C 814'-469'. WOC Tag @ 780'. Spot 45 sx Class C 600'-156'. WOC Tag @ 123'.

9-23-02 Spot 10 sx Class C 60'- Surface.

Cut off & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Kent Whitmire TITLE Operations Spec./Supervisor DATE 11/8/02

Type or print name Kent Whitmire Telephone No. (505) 677-3642

(This space for State use)

APPROVED BY [Signature] TITLE Wildcat Spec. ID DATE DEC 3 1 2002

Conditions of approval, if any:

Post P&H

éLâ≡éⁿâ é?âé♥_T ↑é ⊥▷é ♥|♥? nnä≡iLâ≡âⁿé _T?→â £|? ♥éLâ≡eⁿâ é?â|♥
⊥♥↑é ⊥L↔|L ♠|