Submit 3 Copies to Appropriate District Office

State of New Mexico Jinerals and Natural Resources Department Form C-103 Revised 1-1-89

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St. Santa Fe, NM 87505

VELL API NO. 30-015-02126		
Indicate Type of Lease	STATE	FEE

DISTRICT II		36	anta re, iv	IIVI O7	J0J		sindicate Type of Lea	150	
P.O. Drawer DD, Artesia, NM 88210								STATE	FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 874	110						∘State Oil & Gas Lea		=
CI INDOV	NOTICES	AND DED	ORTS ON	MEL	<u> </u>		79	7.0	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7Lease Name or Unit Agreement Name				
	OKM C-101) I	FOR SUCH PI	RUPUSALS.	.)	 		Artesia Unit		
1Type of Well: OIL GAS WELL OTHER WIW									
Name of Operator V SDX Resources, Inc.							eWell No.	-4	
Address of Operator	70704					Ì	Pool name or Wildon Artesia QN-GB		
PO Box 5061, Midland, TX 4Well Location	17104						1 ,410014 414-00	(00200)	
1	2310 Feet !	From The	South		Line and	330	Feet From The	East	Line
Section	35	Township	178		lange	28E	NMPM	Eddy	County
en e		10Elevation	n (<i>Show whet</i> l	her DF, i	RKB, RT, GR, etc	;.			
11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data									
NOTICE C	OF INTEN	ITION TO) <u>:</u>			SUBS	SEQUENT RE	EPORT OF:	
PERFORM REMEDIAL WORK		PLUG AND AE	BANDON	X	REMEDIAL WO	DR K		ALTERING CASIN	· G
TEMPORARILY ABANDON		CHANGE PLA	\NS		COMMENCE	RILLING O	PNS.	PLUG AND ANBAN	IDONMENT
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB					
OTHER:					OTHER:				
12Describe Proposed or Completed C work) SEE RULE 1103.	Operations (Clea	arly state all pert	tinent detalls, i	and give	pertinent dates,	including es	stimated date of starting	g any proposed	······································
P&A Proposal:							<u> </u>	10111273747	
Set CIBP @ 2150' & cap w/	/40 sx. TOC /	ത 1600'					(2) 83°	4 5%	
TIH & spot 25 sx plug from		<u>.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>					345	10311273747576 A	1819
Cut 4-1/2" csg @ appx 700"							00	D'CCEIVED)20
Spot 35 sx plug from 700		.545	TAG					RECEIVED ARIESIA	27/2/2
Spot 10 sx inside 7" and 10								10000000000000000000000000000000000000	"/
Install marker								4000	
* Brine ael bet	ween al	Il cement	T Plug	s .					
Hereby certify that the information	above is true a	nd complete to t	the best of my	knowled	ige and belief.		<u> </u>		
SIGNATURE STATES	1 m	ngu		тг	TLE Engineer	•		DATE 02-10-	00
TYPE OR PRINT NAME Chuck MO	organ							тецерноне но. 91	5/685-1761
(This space for State Use)					· · · · · · · · · · · · · · · · · · ·				
APPROVED BY TOUS	المالية المالية			TI	TLE Field	Rep. II	,	DATE Z/ZY	1/2000
CONDITIONS OF APPROVAL, IF ANY:	maple				- <u> </u>				

* Notifie NMOCD to witness Plugging Operations.

Artesia Unit # 20 2310' FSL & 330 FEL Sec. 35 T17S R28E Edy Co., N.M.

Existing Condition:

9-3./4" hole to 598' with 598' of 7" csg cemented with 75 sxs. (TOC calculated at 270'.) 6-1/4" hole to 2525 with 2525' of 4-1/2" casing cemented with 200 sxs. (TOC 780' by log) Perfs: 2230'-2508.

2-3/8" PC tubing with Johnson 101-S at 2133'.

Formation Tops: Seven Rivers: 1113'

Queen: 1657' Grayburg: 2129' San Andres: 2505'

P&A Proposal:

- 1.) Set CIBP at 2150' and cap with 40 sxs. TOC at 1600'
- 2.) TIH and spot 25 sx. Plug from 1150-780'.
- 3.) Cut 4-1/2" casing at ~700' and pull.
- 4.) Spot 35 sx. Plug from 700-545'.
- 5.) Spot 10 sx inside 7" and 10 Sxs outside 7" at surface.
- 6.) Install marker.