

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons. **CISF**  
N.M. Div-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
 Oil Well  Gas Well  Other

2. Name of Operator  
Vintage Drilling LLC

3. Address and Telephone No.  
P.O. Box 158 Loco Hills, NM 88255 505-746-1669

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)  
1980' FSL and 860' FEL  
Sec 15, T16S, R29E

5. Lease Designation and Serial No.  
NM 05523

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

High Lonesome Penrose Unit #1

9. API Well No.

30-015-02718

10. Field and Pool, or Exploratory Area

High Lonesome Queen

11. County or Parish, State

Eddy County, NM

12 CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- Notice of Intent
- Subsequent Report
- Final Abandonment Notice

TYPE OF ACTION

- Abandonment
- Recompletion
- Plugging Back
- Casing Repair
- Altering Casing
- Other
- Change of Plans
- New Construction
- Non-Routine Fracturing
- Water Shut-Off
- Conversion to Injection
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plug 1897' - 1997'

\*Perforate @ 875' & set solid plug 775' - 875' Tag.

\*Perforate @ 481' & set solid plug 381' - 481' Tag.

0-50' surface plug

Install dry hole marker

\*Perforate means to perforate & squeeze w/sufficient cement (+/- 40 sks) to have a solid plug outside & inside the casing. Surface casing shoe plugs should have enough cement to circulate to the surface in the annulus between the 8 5/8" surface casing & the production casing.

8 5/8" 24# 431' W/75 sks  
7" 20# 1783' Pulled  
5 1/2" 14# 1969' W/100 sks  
Open Hole 1969' to 1997'

Accepted for Record  
2-27-02

14. I hereby certify that the foregoing is true and correct

Signed *David R. Glass*

Title Secretary

Date 2/15/02

(This space for Federal or State office use)

Approved (ORIG. SGD) DAVID R. GLASS

Title

Date

FEB 19 2002

SEE ATTACHED FOR

CONDITIONS OF APPROVAL

Title 18 U.S.C Section 1001. makes it a crime for any person knowingly and willfully to make (or an) department or agency of the United States any false, fictitious or fraudulent statements or representation & as to any matter within its jurisdiction

DAVID R. GLASS  
PETROLEUM ENGINEER

• See Instruction on Reverse Side