


(SUBMIT IN TRIPLICATE)

Land Office RoswellLease No. 068677

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

R 29 E

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Temporary abandonment</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 31, 1955

Well No. 1 is located 1980 ft. from N line and 660 ft. from E line of sec. 153 3/4 NW 1/4 15
(1/4 Sec. and Sec. No.)16S
(Twp.)29E
(Range)

(Meridian)

Undesignated
(Field)Elly
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3695.01 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On October 27, 1955 the cement and shoe was drilled with air with a 4 3/4" bit on the 5 1/2" production string. While preparing to go in with a core barrel to core the pay section, the core barrel and a chain was dropped in the hole from the surface. The core barrel was 4 1/4" OD X 30' having a diamond bit on bottom and an eye bolt socket on top. The chain was 1/2" X 21' with hooks and followed the core barrel in on top. Unable to fish anything out by October 30, 1955. Management decided to skid and drill another hole temporarily abandoning this hole.

This was approved in a conversation by telephone with Mr. Frost Saturday evening October 29, 1955

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Moab Drilling CompanyAddress Fox 886Artesia, New MexicoBy Robert F. EvansTitle Geologist