

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2068
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	1
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease	
State ☐	For ☒
5. State Oil & Gas Lease No. NM 05523	

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER - injection		AUG 14 1980		7. Unit Agreement Name High Lonesome Penrose	
2. Name of Operator D. W. Berry		O. C. D.		8. Farm or Lease Name High Lonesome Penrose	
3. Address of Operator 1503 Sears Ave. Artesia, NM 88210		ARTESIA, OFFICE		9. Well No. 3	
4. Location of Well UNIT LETTER A 990 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 15 TOWNSHIP 16S RANGE 29E NMPM.				10. Field and Pool, or Wildcat High Lonesome	
15. Elevation (Show whether DF, RT, GR, etc.)				12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Wellhead survey
1" pipe to surface**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **D. W. Berry** TITLE **Owner and operator** DATE **8/13/80**

APPROVED BY **B. W. Weaver** TITLE **CORRELATION UNIT SUPERVISOR** DATE **AUG 25 1980**

CONDITIONS OF APPROVAL, IF ANY: