

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Cons. N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88240
FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
Designation and Serial No.
NM 05523

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Vintage Drilling LLC

3. Address and Telephone No.

P.O. Box 158 Loco Hills, NM 88255 505-746-1669

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)

990' FSL and 660' FEL
Sec 15, T16S, R29E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

High Lonesome Penrose Unit #4

9. API Well No.

30-015-02731

10. Field and Pool, or Exploratory Area

High Lonesome Queen

11. County or Parish, State

Eddy County, NM

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug 1896' - 1996'

*Perforate @ 875' & set solid plug 775' - 875' Tag.

*Perforate @ 486' & set solid plug 386' - 486' Tag.

0-50' surface plug

Install dry hole marker

*Perforate means to perforate & squeeze w/sufficient cement (+/- 40 sks) to have a solid plug outside & inside the casing. Surface casing shoe plugs should have enough cement to circulate to the surface in the annulus between the 8 5/8" surface casing & the production casing.

8 5/8" 24# 436' W/100 sks

7" 17# 1829' Pulled

5 1/2" 14# 1969' W/100 sks

Open Hole 1969' to 1996'

Accepted for Record
2-27-02

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass Title Secretary Date 02/15/02

(This space for Federal or State office use)

Approved by
Conditions of Approval

DAVID R. GLASS
ONR. SEC.

Title

Date

FEB 19 2002

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Title 18 U.S.C Section 1001. makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representation as to any matter within its jurisdiction

DAVID R. GLASS
PETROLEUM ENGINEER

• See Instruction on Reverse Side