

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 9 1970

O.C.C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8889
7. Unit Agreement Name
8. Farm or Lease Name Moab State
9. Well No. 1 J
10. Field and Pool, or Wildcat High Lonesome O.G.S.
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER-
SUN OIL COMPANY - DX DIVISION

2. Name of Operator
Sun Oil Company DX Division NAME CHANGED TO SUN OIL COMPANY

3. Address of Operator
Box 1416 Roswell New Mexico 88201 P.O. BOX 2880
907 S. Detroit Avenue, Tulsa, Oklahoma DALLAS, TEXAS 75201

4. Location of Well
UNIT LETTER J 1980 FEET FROM THE S LINE AND 1980 FEET FROM
THE E LINE, SECTION 16 TOWNSHIP 16S RANGE 29E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

EFFECTIVE DATE TO: SUN OIL COMPANY - DX DIVISION NAME CHANGED TO SUN OIL COMPANY PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
--	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to set 30 sack cement plug at bottom, then cut the 5½ at apporximately 1400' and set 25 sack cement plug at cut-off point, set a 25 sack cement plug at the base of the 8 5/8, and a 10 sack cement plug at the surface, the intervals between the plugs to be filled with mud.

Notify N.M.O.C.C. in sufficient time to witness

* Plugging operations

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. G. Young TITLE _____ DATE February 2, 1970

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE FEB 9 1970

CONDITIONS OF APPROVAL, IF ANY: * as noted above