

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 4 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 2 |

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 9 1970

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK OR TO PERFORM REMEDIAL WORK. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | | | | |
|--|--|---|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | | SUN OIL COMPANY - DX DIVISION | | 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> | |
| 2. Name of Operator Sun Oil Company DX Division | | NAME CHANGED TO SUN OIL COMPANY | | 5. State Oil & Gas Lease No. E- 8889 | |
| 3. Address of Operator 907 S. Detroit Avenue Tulsa, Oklahoma | | P. O. BOX 2880 DALLAS, TEXAS 75201 | | Unit Agreement Name | |
| 4. Location of Well UNIT LETTER 0 660 FEET FROM THE S LINE AND 1980 FEET FROM THE E LINE, SECTION 16 TOWNSHIP 16S RANGE 29E NMPM. | | | | 8. Farm or Lease Name Moab State | |
| | | | | 9. Well No. 20 | |
| | | | | 10. Field and Pool, or Wildcat High Lonesome C-G-SA | |
| | | 15. Elevation (Show whether DF, RT, GR, etc.) | | 12. County Eddy | |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

EFFECTIVE 4-1-70

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

PULL OR ALTER Casing ☐ NAME CHANGED TO ☒

CHANGE PLANS ☐

OTHER ☐

SUN OIL COMPANY - DX DIVISION

SUN OIL COMPANY

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to set 30 sack cement plug at bottom, then cut the 5 1/2 approximately 1400' and set 25 sack cement plug at cut-off point, set a 25 sack cement plug at the base of the 8 5/8, and a 10 sack cement plug at the surface, intervals between plugs to be filled with mud.

Notify N.M.O.C.C. in sufficient time to witness
* plugging operations

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE DATE February 2, 1970

APPROVED BY W.A. Gressett TITLE OIL AND GAS INSPECTOR DATE FEB 9 1970

CONDITIONS OF APPROVAL, IF ANY:

* annotated above