

Form 9-331a
(Feb. 1951)Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Los AlamosLease No. 0016Unit **RECEIVED**

OCT 24 1960

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA, NEW MEXICO

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 16, 1959

Simmons Federal

Well No. 2 is located 330 ft. from N line and 330 ft. from E line of sec. 2424 16S 20E 10N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Almont 1600 New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3720 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The subject well was plugged as follows:

10 sx plug 3120-75
 15 sx plug 1900-80
 7" pipe pulled
 15 sx plug 1800-45
 15 sx plug 550-600
 8 5/8" pipe pulled
 5 sx plug @ surface

Mud was placed between all plugs. A 4' x 4" marker was placed on the well indicating: operator, location, etc.. The location was cleaned up and ready for inspection September 15, 1959.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John M. KellyAddress Box 5671Loswell, New Mexico

By

*Samuel D. McLean*Title Production Superintendent