

N. M. O. & G. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLIC.
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

RECEIVED 77(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

MAY - 8 1980

7. UNIT AGREEMENT NAME

O. C. D.

8. NAME OF LEASEE

Lever

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Cave

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33 T 16 R 29

12. COUNTY OR PARISH

Eddy

13. STATE

N.Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
JEM Resources Inc.

3. ADDRESS OF OPERATOR
Box 648, Artesia, N.Mex. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**1980' from S, and 660' from W. line of Sec. 33
T.16 S R 29 E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8 5/8 surface set at 352' and circulated. 5 1/2 casing set at 2200
with 100 sacks.

Set 25 sacks at 2250 and tagged plug at 2038'. Shot pipe 1250 and set
35 sacks stub plug. Set 35 sacks at 640' and 35 sacks at 360 and tagged
at 330. Set 10 sacks and marker at top.

RECEIVED
AUG 12 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Pres.

DATE

8-12-76

(This space for Federal or State office use)

(Orig. Fed.) **GEORGE H. STEWART**

TITLE

ACTING DISTRICT ENGINEER

DATE

MAY 07 1980