

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N. M. O. C. C. COPYSUBMIT IN TRIPLICATE
(Other instruction: reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WATER INJECTION2. NAME OF OPERATOR
CONTINENTAL OIL COMPANY3. ADDRESS OF OPERATOR
Box 460, HOBBS, N.M. 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FENCE 660' FENCE

RECEIVED

APR 14 1976

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE G-5A

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

SEC. 34, T-16S, R-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3661' DF

O. C. C.

ARTESIA, OFFICE

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

There are no remaining commercial reserves on this lease. All wells will be plugged; the above named well by the following procedure:

Remove tubing. Run tubing w/cement retainer to set @ 2200'. Squeeze open hole w/150 sks. Class "C" cmt. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer.

Pull tubing to 500' & spot 100 sks plug to set. Erect Dry Hole marker.

(No casing will be removed).

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

SR. ANALYST

DATE

12-10-75

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APR 13 1976

H. L. BEEKWIND

DISTRICT ENGINEER

RECEIVED

DEC 12 1975

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOArtesia
HCC & Paulson E. & O.