

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN CTR.
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-013
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-064832

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Forest Pool Unit

8. FARM OR LEASE NAME

Forest Pool Unit

9. WELL NO.

18

10. FIELD AND POOL, OR WILDCAT

Square Lake Grbq SA

11. SEC., T., R., OR BLM. AND
SURVEY OR AREA

Sec. 34-T-16S-R29E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a new reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAY 22 '89

C. C. D.
ARTESIA, OFFICE

330 FSL 1650 FEL

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Marbob Energy Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 217, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3637' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log (Form 3160-6))

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and points pertinent to this work.)

We propose to plug & abandon as follows:

Set cmt plug from TD-2400' (tag), set 100' plug @ 1300-1200', perf csg @ 870' and try to break circulation and circ cmt to surface. If cannot circ, will perf csg & try again. Install dry hole marker and clean location.

RECEIVED
MAY 1 10 33 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 5/2/89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

FOR: TITLE

DATE 5-18-89

*See Instructions on Reverse Side