

FOLD

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
H. C. M. E.						

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from Surface feet to 5041 feet, and from _____ feet to _____ feet

DATES

_____, 19____ Put to producing _____, 19____

The production for the first 24 hours was None barrels of fluid of which _____ % was oil; _____ % emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. _____

If gas well, cu. ft. per 24 hours None Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

F. Sloan _____, Driller EMPLOYEES Roy Blackstock _____, Driller
E. P. Fulton _____, Driller _____, Driller


FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
Surface	45	45	Red Bed-
45	160	115	Red Shale
160	220	60	Red Bed
220	295	75	Anhydrite & Gypsum (Water)
295	320	25	Gypsum
320	360	40	Anhydrite & Red Rock
360	382	22	Anhydrite
382	820	432	Salt
820	1570	750	Anhydrite
1570	1600	30	Red Rock
1600	1715	15	Anhydrite
1615	1620	5	Red Rock
1620	1805	185	Anhydrite
1805	1825	20	Red Sand (Water)
1825	1830	5	Anhydrite
1830	1860	30	Lime
1860	1895	35	Anhydrite
1895	1910	15	Lime
1910	1935	25	Anhydrite
1935	1946	11	Anhydrite - Red Rock
1946	2072	126	Anhydrite
2072	2080	8	Salt
2080	2135	55	Anhydrite
2135	2160	25	Anhydrite - Red Rock
2160	2205	45	Anhydrite

RECEIVED

APR 14 1969

G. C. C.
ARTESIA, OFFICE



CONTINUED ON REVERSE