

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to produce a well. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☐ GAS ☐ WELL ☐ OTHER ☒ WATER INJECTION WELL

2. NAME OF OPERATOR
LAYTON ENTERPRISES, INC.

3. ADDRESS OF OPERATOR
3103 79TH ST. LUBBOCK, TEXAS 79423

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 2130' FSL 660 FEL

5. ELEVATIONS (Show whether LF, RT, GR, etc.)
EA - 165 - 29E

14. PERMIT NO. 3656 GL

15. FIELD AND POOL, OR ACREAGE
SQUARE LARK GEL

16. COUNTY OR PARISH 13. STATE
ECDOY NM

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

INTEND TO PLUG & ABANDON WELL AS FOLLOWS:

8 5/8" CASING @ 386' w/ 50 SX CEMENT

5 1/2" CASING @ 2373' w/ 100 SX CEMENT

1. CIRCULATE HOLE WITH MUD LADEN FLUID

2. SPOT 100 SX CEMENT PLUG THRU TUBING @ 2400'

3. PERFORATE 5 1/2" CASING, BELOW SALT SECTION, @ 960'

4. PUMP 200 SX CEMENT THRU 5 1/2" CASING PERFS @ 900'

& CIRCULATE TO SURFACE LEAVING 5 1/2" FULL OF CEMENT

5. SET SURFACE MARKER

6. CLEAR & LEVEL LOCATION

18. I hereby certify that the foregoing is true and correct

SIGNED Donald E. Layton TITLE PRESIDENT

APPROVED BY [Signature] TITLE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

DEC 13 1983

*See Instructions on Reverse Side

2157

Form approved

Revised 1-2-83 No. 41 B-424

3. LEASE INFORMATION, AND SERIAL NO.

LC-037177 (4)

6. IF INDIAN, ADDRESS OF TRIBE NAME

7. UNIT AGREEMENT NAME

FOREST POOL UNIT

8. FARM OR LEASE NAME

FOREST POOL UNIT

9. WELL NO.

13

10. FIELD AND POOL, OR ACREAGE

SQUARE LARK GEL

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC 34, T16S, R29E

12. COUNTY OR PARISH 13. STATE

ECDOY NM

14. PERMIT NO. 15. FIELD AND POOL, OR ACREAGE

3656 GL SQUARE LARK GEL

16. COUNTY OR PARISH 17. STATE

ECDOY NM

18. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

INTEND TO PLUG & ABANDON WELL AS FOLLOWS:

8 5/8" CASING @ 386' w/ 50 SX CEMENT

5 1/2" CASING @ 2373' w/ 100 SX CEMENT

1. CIRCULATE HOLE WITH MUD LADEN FLUID

2. SPOT 100 SX CEMENT PLUG THRU TUBING @ 2400'

3. PERFORATE 5 1/2" CASING, BELOW SALT SECTION, @ 960'

4. PUMP 200 SX CEMENT THRU 5 1/2" CASING PERFS @ 900'

& CIRCULATE TO SURFACE LEAVING 5 1/2" FULL OF CEMENT

5. SET SURFACE MARKER

6. CLEAR & LEVEL LOCATION

18. I hereby certify that the foregoing is true and correct

SIGNED Donald E. Layton TITLE PRESIDENT

APPROVED BY [Signature] TITLE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

DEC 13 1983

*See Instructions on Reverse Side

