November 1983) *ormerly 9-331)	UN D STATES D- D- DEPARTMEN DF THE INTER BUREAU OF LAND MANAGEMEN		5 LEASE DESIGNATION	- 31, 1085 - AND BERTAL NO 					
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME						
1. OIL GAS OTHER WELL OTHER 2. NAME OF OPERATOR Marbob Energy Corporation $\checkmark$			7. UNIT AGREEMENT NAME Forest Pool Unit 8. FARM OR LEAGE NAME Forest Pool Unit						
					3. ADDRESS OF OPERATOR			9. WBLL NO.	
					4. LOCATION OF WELL (Re	217, Artesia, N.M. 88210 port location clearly and in accordance with any	State requirements.*	19 10. FIELD AND POOL, O	R. WILDOAT
See also space 17 below.) At surface 660 FSL 660 FEL			Square Lake G SA 11. BBC, T. B., M., OR BLE. AND STRVBT OR ABBA						
14. PERMIT NO.	15. ELEVATIONS (Show whether D	TT CE etc.)	<u>Sec. 34-7165</u> 12. COUNTY OF PARISE	5-R29E					
	3643' GR		Eddy	N.M.					
16.	Check Appropriate Box To Indicate N	Acture of Nation Barret of							
NO.	TICE OF INTENTION TO :		UNHER LACKS						
TEST WATER SHUT-OFF Fracture treat Shoot or acidize Repair Well	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING V ALTERING CA ABANDONMEN	ASING					
(Other) 17. DESCRIBE PROPOSED OR C proposed work. If w nent to this work.)* Plugged 2203'; p. bleed of pump 130	and abandoned as follows: Si erforated two holes @ 860', f; set 25 sax; plug @ 888'; sax, circulated 15 sax to p. location, ready for inspection RECEIVE AUG 21 0. C ARTESIA.	Completion or Recompleted and give pertinent dates isons and measured and true vertice et 200' plug @ 2530'; pressure up on perfs tag @ 700'; hole in c it. Installed dry ho on. D BY 1986 D.	tag cement @ to 500#, would casing @ 350';	m.) e of starting any s and somes perti-					

## \*See Instructions on Reverse Side



P