		MON OTT, CHANG. C	(a) (CFOrm approved.
	UN ED STATES	SUMMIT IN TRH AT	Budget Bureau No. 1004-0135 Expires August 31, 1985
Form 31605 "November 1983)	UN ED STATES DEPARTMENT OF THE IN	TERIOR (Other, Instruction, in S	LEASE DESIGNATION AND SECIAL NO.
Formerly 9=331)	DEPARTMENT OF THE IT	MENT	LC-037777(B)
	BUREAU OF LAND MANAGE		6. IF INDIAN, ALLOTTEE OR TRIBE NAM!
SUND	RY NOTICES AND REPOR	RTS ON WELLS	
(Do not we this fo	rm for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	such proposals.)	
	Jse All Montrol	RECEIVED	7. UNIT AGREEMENT NAME
OIL GAS	OTHER		Forest Pool Unit
2. NAME OF OPERATOR) OTHER		S. FARM OR LEASE NAME
Marbob Energy	, Corporation	MAY 22 <u>'89</u>	Forest Pool Unit
3. ADDRESS OF OPERATOR			9. WELL NO.
P O Drawer 2	217, Artesia, N.M. 88210		16 10. FIELD AND POOL, OF WILDCAT
A LOCATION OF WELL (Ret	peri location clearly and in accordance wi	th any State requirements. OFFICE	
See also space 17 below At surface	.)		Square Lake Grbg SA
			SURVEY OR AREA
	330 FSL 810 FWL		- 34 M46G P30E
			Sec. 34-T16S-R29E
14. PERMIT NO.	15. ELEVATIONS (Show wh		Eddy N.M.
	36	14' DF	Ludy
16.	Check Appropriate Box To India	cate Nature of Notice, Report, or	r Other Data
		SUBS	EQUENT EMPORT OF:
NO	TICE OF INTENTION TO:	7	HEPAIRING WELL
TEST WATER SHUT-OFF	(WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING
FRACTURE TREST	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ABANDONMENT* X
SHOOT OF ACTUACE	ABANDON*	(Other)	
REPAIR WALL	CHANGE PLANS		plts of multiple completion on Well mpletion Report and Log form.)
(Other)	MANUETED OPERATIONS (Clearly state all I		
proposed work. It i	well is directionally drilled, give subsurfa	ce locations and measured and true ver	tical depths for all markers and gones feerly
nent to this work.) *			
5/2/68	This well was plugged	and abandoned as follows	5:
	Set SV rtnr @ 1750' an	d sqzd w/250 sx cmt, spo	otted
	100 sx to 1500'; sqz 3	45-1500' w/200 sx cmt w/	wooden
	plug on top. Tagged w	ooden plug @ 345'.	
			W.o.
	Cmt data retained from	Halliburton records. I	VO
	records were contained	in well file.	
		ina Install dry hole	marker
	Marbob will set suri p	lug., Install dry hole if \$\phi = 330' and attemptors. inside 4 outside	naikei AC E
	and clean location. per	f.Q=330' and attemp	E to circ.
	to sw	rf. inside 4 outside	
		0	ECEIVED
		105T ID-2 5-12-89	
		2-89)E
			,
		PLA	20 C
			· ·
\wedge			
15. I hereby cestily that t	he foregoing is trop and correct		5/2/20
thon	da Melson TITL	E Production Clerk	DATE
SIGNED /			
(This space for Federa	al or State office page	2 :	DATE 5-19-87
APPROVED BY		2 :	DATE
CONDITIONS OF AT	PROVAL, IF WY:		