

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
N. M. O. C. C.

Form approved by  
Budget Bureau No. 42-1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. RECEIVED

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
CONTINENTAL OIL COMPANY

APR 14 1976

3. ADDRESS OF OPERATOR  
Box 460, Hobbs, N.M. 88340

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1650' FSL & 2310' FWL OF SEC. 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3628' DF

5. LEASE DESIGNATION AND SERIAL NO.

LC 037777(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

FOREST POOL

8. FARM OR LEASE NAME

FOREST POOL UNIT

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE G-SA

11. SEC., T., R., OR BLK. AND SURVEY OR AREA

SEC. 34, T-16S, R-29E

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

There are no remaining commercial reserves on this lease.  
All wells will be plugged; the above named well by the following procedure:  
Remove tubing. Run tubing w/cement retainer to set @ 25-50 sks. Class "C" cmt. Squeeze open hole w/ 25-50 sks. cmt above retainer. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer. Pull tubing to 500' & spot 100 sks plug to ERECT Dry Hole marker. (No casing will be removed).

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

SR. ANALYST

DATE

12-10-75

(This space for Federal or State office use)

APPROVED BY

CONDUCTIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

RECEIVED  
DEC 12 1975  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

APR 12 1976

H. L. BEEKMAN

ACTING DISTRICT ENGINEER

ARTESIA  
USGS-5, Partner, File