

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions  
on reverse side)

Form approved  
Bureau Order No. 1004-0135  
Expires August 31, 1985

45f

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAY 22 '89

O. C. D.  
ARTESIA, OFFICE

6. LEASE DESIGNATION AND SERIAL NO.

LC-037777 (B)

7. IF INDIAN, ALLIANCE OR TRIBE NAME

8. UNIT AGREEMENT NAME

Forest Pool

9. FARM OR LEASE NAME

Forest Pool

10. WELL NO.

9

11. FIELD AND POOL, OR WILDCAT

Square Lake Grbg SA

12. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 35-T16S-R29E

13. COUNTY OR PARISH

Eddy

14. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Marbob Energy Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 217, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1980 FNL 330 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3661' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We propose to plug & abandon as follows:

Set cmt plug from TD-2500', tag plug; perf csg @ 900',  
attempt to get circ and cmt to surface inside & out.  
If cannot circ, perf csg @ 355' and try again. Install  
dry hole marker and clean location.

RECEIVED  
MAY 24 10 55 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

Rhonda Nelson

TITLE

Production Clerk

DATE

5/2/89

(This space for Federal or State of use)

APPROVED BY

Shirley J. Smith

CONDITIONS OF APPROVAL, IF ANY:

FOR:

TITLE

PRODUCTION CLERK

DATE

5-18-89

\*See Instructions on Reverse Side