## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor **Betty Rivera** Cabinet Secretary

Lori Wrotenbery Director Oil Conservation Division

Field Inspection I wrenen "Preserving as subspects of the Eucliemann

07-Oct-02

CFMOILCO PO BOX 1176 ARTESIA NM 88210-

Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

into 2 Well Stantio NIC - Some dut placed over Spill lenkover.

INSPECTION DETAIL SECTION

(Lew one Rd

Inspection Inspection

Inspection Inspection Please be advised that failure to comply with this directive will result in an application for an order to Show C Bond should not be forfeited, the well plugged and civil penalties assessed.

**FOREST POOL UNIT 022** 

Inspection Date

Type Inspection Routine/Periodic

No

11/7/2002

iMLB0227753054

Comments on Inspection:

No well sign. Violation Rule 103. Area at well head is heavily oil saturated and requires remediation. Violation Rule 13 and rule 116.

**MORGAN STATE 001** 

Inspection Date

10/04/2002

Type Inspection

Mike Bratcher

Violation?

Yes

30-015-02852-00-00 \*Significant

Corrective Action Due By:

Inspection No.

10/04/2002 Routine/Periodic Comments on Inspection:

Mike Bratcher

Yes

No

Non-Compliance?

11/7/2002

iMLB0227754798

Well sign is not mounted and operator name is illegible. Violation Rule 103. PJ-Oper.