

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 11 1972

O. C. C.

ARTESIA, OFFICE

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Water in Section</u>		5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator <u>Mobil Oil Corporation</u>		5. State Oil & Gas Lease No. <u>E-5131</u>
3. Address of Operator <u>Box 633, Midland, Texas 79701</u>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>U</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>16-S</u> RANGE <u>30-E</u> NMPM.		8. Farm or Lease Name <u>West Henshaw Premier Unit Tract 15</u>
		9. Well No. <u>21</u>
		10. Field and Pool, or Wildcat <u>Henshaw Grayburg West</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Eddy</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plug and abandon as per attached Procedures

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 12-8-72

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE DEC 12 1972

CONDITIONS OF APPROVAL, IF ANY:

* as noted on attachment

Notify N.M.O.C.C. in sufficient time to witness

Plugging

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: WEST HERSHAW PREMIER UNIT Well No. 15-2
Field: WEST HERSHAW
County: EDDY State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. SPOT 100' CEMENT PLUG AT BOTTOM
2. CIRCULATE HOLE TO MUD LADEN FLUID
- * 3. CUT OFF & PULL FREE 2 7/8" AT 555'
SPOT 100' CEMENT PLUG
4. SPOT 10 5/8" PLUG AT SURFACE.
5. REMOVE WELL HEAD & INSTALL MARKER


* Cut & pull 2 7/8" from at least base of the salt
spot 100' plug @ base of salt
" 100 plug from 440-540

NOTE: VERBALLY APPROVED BY NHOCC OF ARTESIAN.

15-2

EXHIBIT 4 - F
INJECTION WELL COMPLETION DATA

HUMBLE STATE BC 2
OPERATOR LEASE WELL NO.
LOCATION u - Sec 2 - T 165 - R 30 E
WEST HENSHAW UNIT, EDDY CO., N.M.



R.W. White 2-11-66